



## **101 P7 WATER LEVEL METER**

For measuring the depth of water in wells, boreholes, and standpipes, the Model 101 Water Level Meter is the most accurate and reliable meter. It is sturdy, easy-to-repair and read to 1/100 ft. or to each millimeter.

- 101 P7 Submersible Probe measures water levels and total well depth
- More consistent measurements with sensor located at the tip of probe
- Solinst PVDF flat tape has increased tensile strength and electrical efficiency



+62 821 4486 1199

For More Information sales02@totalenviro.co.id

Visit Us totalenviro.co.id